

63-67 Front Repair Panels

These repair panels are used when the top surround panel is not being replaced.

| | | |
|---|---------|--------|
| A LH Top Fender Panel MM 2O/S | 8200363 | 369.50 |
| B RH Top Fender Panel MM 2O/S | 8200364 | 369.50 |
| C Center Nose Panel MM O/S | 8200365 | 199.95 |
| Center Wiper Panel MM O/S | 8200366 | 127.50 |
| D Door to Door Wiper Panel MM O/S | 8200367 | 224.50 |
| Head Lamp Header Bar Parts: | | |
| E Steel Reinforcement Beam O/S | | |
| Supports the head lamp end plates | 8200312 | 105.00 |
| Steel Beam with Bonding Strip O/S | | |
| Bonds to top surround panel. MM | 8200320 | 199.75 |
| F Header Bonding Strip Only MM O/S | 8200321 | 86.50 |
| Head Lamp Steel End Plates: | | |
| LH Outer Steel End Plate | 8200316 | 30.00 |
| LH Inner Steel End Plate | 8200317 | 30.00 |
| RH Outer Steel End Plate | 8200318 | 30.00 |
| RH Inner Steel End Plate | 8200319 | 39.95 |

Head Lamp End Plate Bonding Strips:

| | | |
|---------------------------|---------|-------|
| LH Outer End Plate B/S MM | 8200322 | 29.90 |
| LH Inner End Plate B/S MM | 8200323 | 29.90 |
| RH Outer End Plate B/S MM | 8200324 | 29.90 |
| RH Inner End Plate B/S MM | 8200325 | 29.90 |


Key LH= Left drivers side RH = Right side
 B/S = Bonding Strip
 MM = Match Molded, smooth both sides
 HL = Hand Laid fiberglass smooth 1 side
 * = Shipped by Truck, freight collect
 O/S = Oversize 2O/S = Double Oversize
Note: These panels are available in colors
 63-64 White - 65-66 Gray - 67 Black

63-67 Inner Fender Skirts

| | | |
|--|---------|--------|
| 63 LH Inner Skirt O/S MM | 8200422 | 329.95 |
| 63 RH Inner Skirt O/S MM | 8200423 | 329.95 |
| 64 LH Inner Skirt O/S MM | 8200426 | 329.95 |
| 64 RH Inner Skirt O/S MM | 8200427 | 329.95 |
| 65 LH Inner Skirt O/S MM | 8200372 | 329.95 |
| 65 RH Inner Skirt O/S MM | 8200375 | 329.95 |
| 66-67 LH Inner Skirt O/S MM | 8200373 | 329.95 |
| 66-67 RH Inner Skirt O/S MM | 8200376 | 329.95 |
| 63-67 LH Inner Skirt O/S HL | 8200374 | 269.00 |
| 66-67 RH Inner Skirt O/S HL | 8200377 | 269.00 |
| 63-67 LH Inner Skirt Battery Access Panel Only with AC or 65 396 Only MM | 2333120 | 89.00 |
| Panel With T-Nuts Installed MM | 2333128 | 129.00 |

63 Upper Skirt to Top Surround Bonding Strip 4 Piece Set
 MM Available separately below 8200370 172.50

| | | | | |
|--------------|---------|----|---------|-------|
| Front B/S LH | 8200394 | RH | 8200395 | 44.50 |
| Rear B/S LH | 8200396 | RH | 8200397 | 44.50 |



Y 63-67 Fender Tip Set replaces the pieces removed when Side Exhaust was Installed. Includes Front & Rear Tips, For LH & RH Sides. MM 8200368 179.95

| | | | | |
|--------------|---------|----|---------|-------|
| Front Tip LH | 8200452 | RH | 8200453 | 47.50 |
| Rear Tip LH | 8200454 | RH | 8200455 | 47.50 |

63-67 Front Fiberglass

63-67 Top Surround Panels Truck Ship *

| | | |
|--|------------|------------------|
| GM Replacement Panel MM | 8200301 | 775.00 |
| K Reproduction Panel MM | 8200302 | 1079.95 |
| KEF Panel with Header Bar & B/S | 8200371 | 1395.00 |
| L 63 Head Lamp Housing Outer Skin Only: | | |
| HL LH 8200314 | 79.50 | RH 8200315 79.50 |
| M 63 Hood Wedge Fender Supports Bonding Strips | | |
| MM LH 8200309 | 44.50 | RH 8200310 44.50 |
| Front Fender Louver Panels: All are MM UPS O/S | | |
| Select from two different brands of MM Fiberglass. | | |
| N 63-64 Image LH 8200116 | RH 8200117 | 239.50 |
| N 63-64 Sermer LH 8200326 | RH 8200327 | 274.50 |
| O 65-66 Image LH 8200089 | RH 8200090 | 239.50 |
| O 65-66 Sermer LH 8200328 | RH 8200329 | 294.50 |
| P 67 Image LH 8200091 | RH 8200092 | 239.50 |
| P 67 Sermer LH 8200330 | RH 8200331 | 299.50 |
| Q 63-67 Top Surround to Side Fender Panel Bonding Strips | | |
| These have the authentic reliefs and notches. | | |
| MM LH 8200334 | 84.50 | RH 8200335 84.50 |
| R Corner Nose Parking Lamp Panel: all are MM O/S | | |
| Specify year & allow the following approximate delivery. | | |
| 63-64 2 weeks LH 8200338 | RH 8200339 | 172.50 |
| 63-64 8 weeks LH 8200682 | RH 8200683 | 204.00 |
| 65-67 2 weeks LH 8200340 | RH 8200341 | 172.50 |
| 65-67 8 weeks LH 8200684 | RH 8200685 | 204.00 |
| S 63-67 Wheel Well Lip to Parking Lamp Panel Bond Strip | | |
| MM LH 8200342 | 69.50 | RH 8200343 69.50 |
| T 63-67 Center Upper Grill Panel Between the Head Lamps MM O/S 8200346 109.95 | | |
| U 63-67 Center Upper Grill Bonding Strip to the Top Surround Panel MM 8200347 59.50 | | |
| Center Lower Valance Panel Below Grill | | |
| V 63-64 Center Lower Panel MM O/S | 8200349 | 132.00 |
| W 65-67 Center Lower Panel MM O/S | 8200350 | 132.00 |
| X 63-67 Lower Grill to Parking Lamp Bonding Strip | | |
| These small bonding strips are discontinued genuine GM. | | |
| MM LH 8200351 | 24.50 | RH 8200352 24.50 |

Truck Ship Prices Include the Crating Fee

